

Sennebogen 821 overslagkraan

General features

Brand	Sennebogen
Subcategory	Material handler
Construction year	2020
Hourmeter reading	12230
Color	White
Condition	Used
General condition	Good
Fuel	Diesel



Sennebogen 821 overslagkraan

Technical specifications

Drive wheels

Accessories